



QFT LABORATORY, LLC

41 D Germay Drive, Wilmington DE 19804
PHONE 856-583-0445 www.enviroteklab.com
EPA ID # DE00946 NJDEP ID # DE009 IAPMO ID #102

CARICO WHOLE HOUSE FILTER SEAL VERIFICATION TEST REPORT

Report # 18-526
Report Date: 11/02/2018
Customer Name: Carico.

Contaminant Tested	Influent Water	10 gallons	20 gallons	30 gallons	40 gallons	50 gallons	% Reduction @ 50 gallons
Total Chlorine Test (mg/L)							
Raw Material Test (No housing)	1.80 ppm	<0.01	<0.01	<0.01	<0.01	<0.01	>99.4%
Head with New Tank #1	2.20 ppm	0.04	0.04	0.02	0.02	0.02	99.1%
Head with Old Tank #2	2.20 ppm	0.04	0.05	0.04	0.04	0.04	98.2%

Flow Rate: 1.0 gpm
Cycle: 20 min on: 20 min off
Total volume tested: 50 gallons.

CERTIFICATION OF RESULTS:

I certify in writing that all analyses, and reporting performed herein, comply with all requirements set forth in NSF/ANSI Std 42, 53, 401, and hereby certify that this laboratory is in compliance with all laboratory certification and quality control procedures and requirements as set forth in the NYCRR Subpart 55-2, the National Environmental Laboratory Accreditation Conference (NELAC) Institute Standards, the Water Quality Association (WQA), and IAPMO, ISO 17025.

Disclaimer: The test results are only related to the filter tested, in the condition received at the laboratory.

Jaime Young
Lab Director